




Rebar installation, concrete slab and footing pours ongoing in Large Venue.



The contractor is surveying the existing structural columns and piers to determine need of reinforcement.



Continued rebar installation in the Large Venue.



2nd Floor Large Venue Grid Iron hanging is in progress.

